State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

For ok

Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD) **INSPECTION REPORT**

Partial:	Comp	olete: XXX	Exploration:
Inspection Date	& Time:	09/25/2001	9:30a.m11:30p.m.
		ction: 08/2	

Mine Name: Hidden Valley Mine County: Emery Permit N	umber: <u>C/015/007</u>						
Permittee and/or Operator's Name: Consolidation Coal Company							
Business Address: P.O. Box 566, Sesser, Illinois 62884							
Type of Mining Activity: Underground XXX Surface Prep.	Plant Other						
Company Official(s): Steve Behling							
State Official(s): Susan White Federal Official(s): None							
Weather Conditions: Temp 80's and blue sky							
Existing Acreage: Permitted 960 Disturbed 7 Regraded	Seeded						
Status: Active XXX							

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	П	[X]	П
2.	SIGNS AND MARKERS	[X]	$\overline{\Box}$	\Box	П
3.	TOPSOIL	П	<u>[X]</u>	П	П
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	Ц	[X]	П
	b. SEDIMENT PONDS AND IMPOUNDMENTS		$\overline{[X]}$	П	П
	c. OTHER SEDIMENT CONTROL MEASURES	[X]		[X]	\prod
	d. WATER MONITORING	$\overline{[X]}$	\Box	[X]	П
	e. EFFLUENT LIMITATIONS		<u>[X]</u>	П	
5.	EXPLOSIVES	Π	[X]	\Box	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		[X]	\Box	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		Ц	П	\Box
8.	NONCOAL WASTE	[X]	Ш	\Box	П
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]	\Box	Ц	\Box
10.	SLIDES AND OTHER DAMAGE	<u> </u>	[X]	П	П
11.	CONTEMPORANEOUS RECLAMATION	[X]	\Box	\Box	
12.	BACKFILLING AND GRADING	[X]	Ц	\Box	Ш
13.	REVEGETATION	[X]	П	[X]	
14.	SUBSIDENCE CONTROL	\Box	[X]	П	
15.	CESSATION OF OPERATIONS	[X]	П	П	Ш
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	\Box	[X]	П	\Box
	b. DRAINAGE CONTROLS	\Box	[X]	П	\Box
17.	OTHER TRANSPORTATION FACILITIES	[X]	\Box	П	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	П	[X]	П	
	AVS CHECK (4th Quarter- April, May, June)	[X]	Ц	Ш	П
	AIR QUALITY PERMIT		[X]	П	
21.	BONDING & INSURANCE	[X]	Ц	[X]	\Box

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/007

DATE OF INSPECTION: 09/25/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permit expires January 20, 2002. The application for permit renewal is due at the end of the month.

Mr. Behling reports that reworking of the A seam is unlikely this year.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were stable and a small amount of runoff may have occurred. Some rock from the highwall above seam A had fallen. The diversion above A was functional even though its usefulness is questionable.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Silt fences are in place although their usefulness are questionable.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The MRP requires sampling Ivie Creek above and below the mine in the spring and fall. Sample and field measurements were taken May 18, 2001. Hard copies of the water quality data were submitted to the Division July 26, 2001.

The May data has been entered into the "pipeline" of the Division's water quality database. The Division cannot move the data into the database until the Operator provides the Division written notification.

13. REVEGETATION

The site is very dry. Annual weeds have died and perennial shrubs and grasses are visible.

21. BONDING AND INSURANCE

Insurance expires November 1, 2001. The surety bond is on record for \$90,758 and is effective for the permit period. It is dated January 27, 1987.

Inspector's Signature:

Susan M. White

Date: October 1, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

M. White

cc: James Fulton, OSM

Tim Kirschbaum, Consol, Illinois Steve Behling, Consol, Emery

Price Field office

O:\015007.HID\Compliance\2001\c 0925.wpd